

# Cryogenic Gas & Liquid Nitrogen Safety

- **Burn Hazard**
  - Personal Protective Equipment
    - Hand protection
    - Goggles (not glasses)
    - Full-length pants or apron
    - Closed-toe footwear
- **Asphyxiation Hazard**
  - Dispense in well-ventilated areas
    - Do not carry on elevators
    - Do not leave unattended
- **Explosion Hazard**
  - Do not store in container with tight fitting cap.
  - Dispense only into approved Dewars.